



Арт. 123

Код	A	A1	B	C	D		
12318L22	G1/8	G1/8	6	22	16	14	100
12318L32	G1/8	G1/8	6	32	26	14	100
12318L42	G1/8	G1/8	6	42	36	14	100
12318L51	G1/8	G1/8	6	51	45	14	50
12314L28	G1/4	G1/4	8	28	20	17	50
12314L35	G1/4	G1/4	8	35	27	17	50
12314L51	G1/4	G1/4	8	51	43	17	25




Арт. 125

Код	A	B		
12518	1/8	8,0	13	50
12514	1/4	11,0	17	25
12538	3/8	11,5	20	25
12512	1/2	14,0	25	10




Арт. 126

Код	A	B		
12618	G1/8	8	13	50
12614	G1/4	11	17	25
12638	G3/8	11	20	25
12612	G1/2	14	25	10




Арт. 127

Код	G	A	B	C			
127M5	M5	M10x1,0	10,5	14	14	14	100
12718	G1/8	M16x1,5	14,0	18	22	19	50
12714	G1/4	M20x1,5	21,0	24	27	24	25
12738	G3/8	M26x1,5	21,0	26	32	30	25
12712	G1/2	M28x1,5	27,0	33	36	32	10




Арт. RLB100

Код	G	A	B	L1	L2	
RLB100M5	M5	9	4,5	9	4,5	100
RLB10018	1/8	14	6,5	14	8	100
RLB10014	1/4	18	9	18	10	100
RLB10038	3/8	19	11	19	11,5	50



Арт. 412

Код	A	G*	ØB	ØC	D	H	
41218	G1/8	G1/8	9,9	14	20	15	50
41214	G1/4	G1/4	13,3	18	24	17	50
41238	G3/8	G3/8	16,8	21	28,5	20	25



*присоединение пустотелого болта